

# Interdisciplinary Workshop on Management of Earthquake Risks

August, 28-29, 2006

ETH

Zurich, Switzerland

---

## VULNERABILITY CURVES FOR MONUMENTAL BUILDINGS BASED ON SEISMIC DAMAGE OBSERVATION

Emanuela Curti, Sonia Giovinazzi, Sergio Lagomarsino and Stefano Podestà

*University of Genoa*

*DISEG - Department of Structural and  
Geotechnical Engineering*



# VULNERABILITY ANALYSIS FOR MONUMENTAL BUILDINGS

The damage assessment to monumental buildings, after the recent seismic events in Italy, proved the high seismic vulnerability of this kind of structures and the relevance of their vulnerability assessment for the management of the earthquake risk both from the economic and the cultural point of view




# VULNERABILITY ANALYSIS FOR MONUMENTAL BUILDINGS

The damage assessment to monumental buildings, after the recent seismic events in Italy, proved the high seismic vulnerability of this kind of structures and the relevance of their vulnerability assessment for the management of the earthquake risk both from the economic and the cultural point of view



Vulnerability and seismic risk analysis of monuments should be defined and implemented with the aim to:

- ❑ make decision makers aware of the potential consequences of an earthquake to the cultural heritage
- ❑ list the monuments by seismic vulnerability in order to prioritize preventive interventions for the risk mitigation
- ❑ manage the emergency after an earthquake event, estimating in a short time, the potential damage occurred




Importance of an analysis at **territorial scale**



# VULNERABILITY CURVES for MONUMENTAL BUILDINGS

Aiming at developing observational vulnerability models, related to homogeneous monumental typologies, data available from the damage assessment have been processed



*The same analytical function proposed for ordinary buildings, has been assumed for correlating the expected mean damage grade  $\mu_d$  to the macroseismic intensity for monumental buildings*

**VULNERABILITY CURVE** 
$$\mu_D = 2.5 \cdot \left[ 1 + \tanh \left( \frac{I + 6.25 \cdot V - 13.1}{Q} \right) \right]$$

Statistical analyses of observed damage have been performed in order to identify the vulnerability curve defining parameters :

- ✓ vulnerability index V
- ✓ ductility index Q


# A HOLISTIC APPROACH FOR THE VULNERABILITY ASSESSMENT

	Available information		Vulnerability description	
	Ordinary Buildings	Monuments	Macroseismic approach	Mechanic approach
<b>Level 0</b>	Number of buildings and statistical knowledge of the main features	Typology (church, palace, tower, castle etc.) and expert judgment	Vulnerability index $V$ for each typology	Capacity curve for each typology defined without the use of mechanical methods
<b>Level 1</b>	Existing database with information non specifically surveyed for vulnerability purposes.	A few data related to the seismic behavior and derived from a quick survey specific for the vulnerability assessment	Vulnerability index $V$ , for each single building, refined by taking into consideration behavior modifiers	Capacity curve is evaluated starting from the vulnerability index and accounting for the known structural parameters
<b>Level 2</b>	Detailed information about the typology and the geometrical, structural and technological features from a survey specifically devoted to the vulnerability assessment	More detailed information related both to the building geometry and to the present vulnerability elements	Vulnerability index $V$ for each single building or for each macroelement assessed via an accurate analysis. Specific form are used for the infield vulnerability assessment	Capacity curve derived from mechanical methods usually based on limit equilibrium analysis

# THE 1976 FRIULI EARTHQUAKE (ITALY)

The first experience of safety assessment for monumental buildings was developed for the 1976 Friuli earthquake (Italy).

The seismic sequence began on 6 may 1976 - 6.4 ML  
965 dead - 60000 homeless





S. Stefano di Ceslans church – Cavazzo (UD)

After the main shock, replica tremors involved this area for four months and on September a shock of magnitude ML equal to 6.1 shocked the already damaged structures

During the damage and safety assessment, phenomena of damage accumulation were analyzed in detail, providing a series of indications useful to understand the seismic behavior of this kind of structures

# VENZONE (UD): THE 1976 FRIULI EARTHQUAKE (ITALY)




**Venzone Cathedral:** re-built according to “*anastilos*” methodology: every ashlar has been catalogued and re-located in the original position.



Venzone Cathedral after the first mainshock

**S. Anna and S. Giacomo church:** collapsed after the earthquake, it was not rebuilt in memory of the catastrophic event

# THE 1976 FRIULI EARTHQUAKE (ITALY)



After the seismic event, for the first time, the collected data were catalogued in systematic way. The results of this research are contained in the book: F. Doglioni, A. Moretti, V. Petri, "The churches and the earthquake" (in Italian), published in 1994 (around 20 years after the earthquake).



For each church, on the basis of photographic documentation and data of the survey carried out during the reconstruction phase, the more recurrent damage mechanisms were identified.



**S. Valentino church - Gemona (UD)**



**S.<sup>2</sup> Maria delle Grazie church - Venzone**



3.3



6.54






6.55



6.56

**S. Chiara church - Venzone**

For each church, on the basis of photographic documentation and data of the survey carried out during the reconstruction phase, the more recurrent damage mechanisms were identified.




Venzone Cathedral : damage state after the first shock

From the systematic examination of the damaged churches it was possible to observe that the seismic response of this kind of buildings may be described according to recurrent phenomenology, traceable to the damage modes and mechanisms of collapse of different parts called:

## MACROELEMENTS



Part of the church characterised by a proper seismic response that can be evaluated almost independently from the rest of the structure. The individuation of the macroelement is strictly connected to the observation of the seismic behaviour and generally does not coincide with the architectural elements. In particular we have to consider, beyond the architectural element, an overlap zone in order to describe the constrain degree with the rest of the construction.



SS. Faustino e Giovita church - Botticino Mattina (BS)

## DAMAGE MECHANISMS

**Damage mechanism:** kinematism through which the different parts of the construction (macroelements) come to collapse. Generally (in case of good masonry quality) the damage mechanism can be associated to rotation or sliding between masonry portions, schematized, for easiness, as rigid bodies.



S. Rocco church - Forgaria (UD)

Pignano Church - Ragonga (UD)

Out-of-plane seismic action causes overturning damage mechanisms.

In-plane seismic action induces sliding or shear failures, characterized by oblique ( $45^\circ$ ) cracks

## THE 1997 UMBRIA and THE MARCHES EARTHQUAKE (ITALY)

The Umbria and The Marches seismic sequence is characterized by three main shocks (September 1997 – epicenter Colfiorito; October 1997 – epicenter Sellano; March 1998 – epicenter Gualdo Tadino). More than 1000 churches were damaged by the earthquake (magnitude 5.8). The vaults of S. Francesco d'Assisi Basilica partially collapsed causing the death of 4 people.

The need to survey several monumental buildings, determined, for the first time, the adoption of a specific survey form. The methodology was inspired by the previous experiences, but the damage survey is summarized in a simple and quick form (only 4 pages)



Collapse of S. Francesco d'Assisi vault – Assisi (PG)




S. Rocco - Sellano (PG)



# THE FORM FOR THE DAMAGE ASSESSMENT OF CHURCHES

<b>1. OVERTURNING OF THE FACADE</b>	<input type="checkbox"/>	<b>2. DAMAGE AT THE TOP OF THE FACADE</b>	<input type="checkbox"/>
DETACHMENT OF THE FACADE FROM WALLS	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	CRACKS IN THE TOP PART OF THE FACADE	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Poor clamping between facade and nave walls <input type="checkbox"/> Lack of longitudinal chains or efficient buttresses		<input type="checkbox"/> Facade weakened by wide openings <input type="checkbox"/> Lack of a connection with the roof covering	
<b>3. SHEAR MECHANISMS IN THE FACADE</b>	<input type="checkbox"/>	<b>4. TRANSVERSAL VIBRATION OF THE NAVE</b>	<input type="checkbox"/>
SLOPING, VERTICAL AND ARCHED CRACKS	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	CRACKS IN ARCHES, DEFORMED WALLS	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Presence of many openings (also filled) <input type="checkbox"/> Possibility of rotation of the side walls		<input type="checkbox"/> Very thin side walls <input type="checkbox"/> Lack of transversal chains or efficient buttresses	
<b>5. TRIUMPHAL ARCH</b>	<input type="checkbox"/>	<b>6. VAULTS OF THE NAVE</b>	<input type="checkbox"/>
CRACKS IN KEY AND SPINE	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	CRACKED VAULTS, DETACHMENT FROM ARCHES	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Arch of insufficient thickness or poor masonry <input type="checkbox"/> Chains missing or badly placed; weak shear walls		<input type="checkbox"/> Vaults lowered excessively or thin <input type="checkbox"/> Presence of concentrated loads of roof covering	
<b>7. HAMMERING OF THE ROOF COVERING</b>	<input type="checkbox"/>	<b>8. DOME</b>	<input type="checkbox"/>
BEAM SLIDING; DISCONNECTION OF TIE BEAMS	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	CRACKS IN: DOME, TAMBOUR, LANTERN	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Roof thrusting; new roof covering rigid and heavy <input type="checkbox"/> Lack of connection between tie beams and masonry		<input type="checkbox"/> Tambour very high and with large openings <input type="checkbox"/> Lack of hoops or external buttresses	
<b>9. OVERTURNING OF THE APSE</b>	<input type="checkbox"/>	<b>10. VAULTS IN THE PRESBYTERY OR APSE</b>	<input type="checkbox"/>
VERTICAL OR ARCHED CRACKS IN APSE WALLS	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	CRACKS IN THE VAULT OR APSE BASIN	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Lack of hoops or chaining <input type="checkbox"/> Weakening from many wall openings		<input type="checkbox"/> Vaults lowered excessively or thin <input type="checkbox"/> Presence of concentrated loads by the roof covering	
<b>11. OVERTURNING OF END WALLS</b>	<input type="checkbox"/>	<b>12. LACK OF CONTINUITY IN WALLS</b>	<input type="checkbox"/>
DETACHMENT OF END WALL	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	MOVEMENT OF JOINTS OR DISCONNECTEDNESS	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Poor clamping between wall and orthogonal walls <input type="checkbox"/> Lack of chains or efficient buttresses		<input type="checkbox"/> Great difference of stiffness between two parts <input type="checkbox"/> Lack of clamping or chains	
<b>13. SHEAR FAILURE OF THE WALLS</b>	<input type="checkbox"/>	<b>14. BELL TOWER</b>	<input type="checkbox"/>
SHEAR CRACKS OR LOCAL DISCONTINUITY (OLD OPENINGS etc.)	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	CRACKS ON CONTACT WITH THE CHURCH; VERTICAL CRACKS; EXPULSION OF EDGE	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Masonry poor or of limited thickness <input type="checkbox"/> Great weakening due to the presence of openings		<input type="checkbox"/> Lack of connections with the church <input type="checkbox"/> Masonry decayed, poor, of limited thickness	
<b>15. BELL CELL</b>	<input type="checkbox"/>	<b>16. OVERTURNING OF PROJECTIONS/SPIRES</b>	<input type="checkbox"/>
CRACKED ARCHES; PIER ROTATION OR SLIDING	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	PERMANENT ROTATION OR SLIDING	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
<input type="checkbox"/> Lack of chains or hoops; thin piers <input type="checkbox"/> Roof covering heavy or thrusting		<input type="checkbox"/> Lack of buttress or other connection <input type="checkbox"/> Projection too thin	



The approach for macroelements and damage mechanisms allowed, during inspection operations, the association of the cracks and deformations observed to a particular damage mechanism , more or less developed at the time of the earthquake

the presence of macroelement

1	<b>OVERTURNING OF THE FACADE</b>	<input type="checkbox"/>
Damage	DETACHMENT OF THE FACADE FROM WALLS	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Vulnerability	<input type="checkbox"/> Poor clamping between facade and nave walls <input type="checkbox"/> Lack of longitudinal chains or efficient buttresses	

the level damage: 0 - no damage; 1 - light damage; 2 - medium damage; 3 - severe damage/collapse

the intrinsic vulnerability of the building to that mechanism, through two indicators linked to specific construction weaknesses

# DAMAGE AND VULNERABILITY SCORES

The vulnerability model is synthesized by two indexes obtained through the simple average of levels of damage in the actual macroelements and the vulnerability scores,

**Damage Score:** is a continuous variable between 0 and 1 which measures the average level of damage to the church

$$i_d = \frac{1}{3N} \sum_{k=1}^{16} d_k$$

$d_k$  = is the damage in the  $k$ -th mechanism (from 0 to 3)

$N$  = is the number of mechanisms that can be potentially activated in the church ( $N \leq 16$ ).

**Vulnerability Score:** is linked to the propensity of the church to be damaged by the earthquake

$$i_v = \frac{1}{2N - m} \sum_{k=1}^{16} v_k$$

$v_k$  = are the indicators of vulnerability present in the  $k$ -th mechanism (from 0 to 2)

$m$  = is the number of questions about vulnerability to which it was not possible to reply (for example certain zones of the construction may not be inspected in an emergency or elements to supply a judgement are not available).



In order to make the vulnerability analysis of churches consistent with the one of ordinary buildings in territorial risk analysis, it is necessary to transform the damage score into a discrete variable, that is to establish a correlation with the six levels of damage of the EMS-98 Scale

Level	Damage score	Description of structural damage
0	$i_d \leq 0.05$	<u>No damage</u> : light damage only in one or two mechanisms
1	$0.05 < i_d \leq 0.25$	<u>Negligible to slight damage</u> : light damage in some mechanisms
2	$0.25 < i_d \leq 0.4$	<u>Moderate damage</u> : light damage in many mechanisms with one or two mechanisms activated at medium level
3	$0.4 < i_d \leq 0.6$	<u>Substantial to heavy damage</u> : many mechanisms have been activated at medium level, with severe damage in some mechanisms
4	$0.6 < i_d \leq 0.8$	<u>Very heavy damage</u> : severe damage in many mechanisms, with the collapse of some macroelements of the church
5	$i_d > 0.8$	<u>Collapse</u> : at least 2/3 of the mechanisms exhibit severe damage



DPM, obtained from the data collected in Umbria: 1000 churches

The complete sample has been split into four different groups, with reference to the macroseismic intensities (MCS scale);

The continuous line corresponds to the binomial distribution relative to the mean damage grade of the data set

$$p_k = \frac{5!}{k!(5-k)!} \left(\frac{\mu_D}{5}\right)^k \left(1 - \frac{\mu_D}{5}\right)^{5-k} \quad K = (0, 1, 2, 3, 4, 5)$$


### UMBRIA




Analogously to the buildings, it emerges the good fit of the binomial function to the observed damage distribution

Analogously to the analysis on the Umbria churches, statistical analyses have been made on databases, related to another Italian earthquakes.

## THE MARCHES




Also in this case the histograms are very well fitted by the binomial distribution and the mean damage grades, associated to each macroseismic intensity, are similar to the one representative of churches in Umbria.



As is obvious, this parameter gradually increases with the intensity of the earthquake


The available data are then split by considering the vulnerability score into two classes:  
 A - more vulnerable churches ( $iv \geq 0.4$ ); B - less vulnerable churches ( $iv < 0.4$ ).



## THE MARCHES

For the intensity I=VIII the sample is too scant to assure a significant result from the statistical point of view.


The available data are then spilt by considering the vulnerability score into two classes:  
A - more vulnerable churches ( $iv \geq 0.4$ ); B - less vulnerable churches ( $iv < 0.4$ ).



## THE MARCHES


For the intensity I=VIII the sample is too scant to assure a significant result from the statistical point of view.

The available data are then split by considering the vulnerability score into two classes:  
 A - more vulnerable churches ( $iv \geq 0.4$ ); B - less vulnerable churches ( $iv < 0.4$ ).



## THE MARCHES

For the intensity I=VIII the sample is too scant to assure a significant result from the statistical point of view.



## UMBRIA

the churches of Class A are remarkably more vulnerable than the ones of Class B, confirming the meaningfulness of the vulnerability score.

The choice of considering two vulnerability classes derives from the analogous approach used in MSK scale for the ordinary buildings; the damage of class B, is nearly the same as that in the churches of class A, for an intensity one degree less


$I_{MCS}$	$\mu_D$	UMBRIA				THE MARCHES			
		N°	All	Class A	Class B	N°	All	Class A	Class B
V	1.025	295	1	1.15	0.45	95	1.1	1.4	0.95
VI	1.385	616	1.3	1.8	0.95	779	1.45	2.1	1.15
VII	2.015	245	2.15	2.25	1.5	150	1.8	2.25	1.55
VIII	3	47	2.9	-	-	24	3.2	-	-

## PALACES

$Q = 2.3$	$V_{\max} = 0.79$
	$V = 0.49$
	$V_{\min} = 0.62$

## CHURCHES

$Q = 3$	$V_{\max} = 1$
	$V = 0.89$
	$V_{\min} = 0.78$



The two models confirm what is normally observed after a seismic event: churches are more vulnerable than buildings, especially in the case of low intensity earthquakes. It is worth noting that the values of the denominator in the two function are different; this parameter determines the slope of the curve.




## ARCHIVE RESEARCH

<i>Seismic events</i>	<i>Typologies</i>	<i>Material sources</i>
<b>Irpinia (Italy)</b> November 23, 1980	Churches, Convents, Towers, Castles	SBBA di Potenza - MBC
<b>Lunigiana e Garfagnana</b> October 10, 1995	Churches	Region Tuscany
<b>Umbria and The Marches</b> September 26, 1997	Churches, Convents, Towers, Castles	Region Umbria - MBC
<b>Molise</b> November 1, 2002	Churches, Convents, Towers, Castles	Region Molise - MBC
<b>Piedmont</b> April 11, 2003	Churches	Regione Piedmont – MBC
<b>Lombardy</b> November 24, 2004	Churches	Regione Lombardy – MBC

This archive research has been finalized to individuate, as for the churches, a wide observation information about the damage levels and the collapse modes for other monumental typologies.

# IRPINIA - BASILICATA

Specific survey form: the data collected are very poor but allows the identification of the typology of the monumental building



Damage level:

No Damage	→	-	→	0
Slight Damage	→	A	→	1
Moderate Damage	→	B	→	2
Heavy Damage	→	C	→	3
Collapse	→	D	→	4

**SOPRINTENDENZA AI BENI AMBIENTALI E ARCHITETTONICI**  
**POTENZA** Scheda compilata il \_\_\_\_\_ da \_\_\_\_\_

Pr. \_\_\_\_\_ Comune \_\_\_\_\_ Località \_\_\_\_\_  
 Denominazione \_\_\_\_\_  
 Proprietà \_\_\_\_\_  
 IGMF \_\_\_\_\_ TAV \_\_\_\_\_ Dati catastali F. \_\_\_\_\_ Part. n. \_\_\_\_\_

ACCESSIBILITA'  
 chiusura affidabile  
 chiusura non affidabile  
 chiusura assente  
 sistemi antifurto


TIPOLOGIA		PIANI E DIMENSIONI DI MASSIMA	
<input type="checkbox"/> palazzo <input type="checkbox"/> edilizia tradizionale <input type="checkbox"/> castello <input type="checkbox"/> mura <input type="checkbox"/> torre <input type="checkbox"/> chiesa <input type="checkbox"/> campanile <input type="checkbox"/> casa canonica <input type="checkbox"/> convento <input type="checkbox"/> cappella - edicola	<input type="checkbox"/> interrato <input type="checkbox"/> seminterrato <input type="checkbox"/> fuoriterza <input type="checkbox"/> sottotetto <input type="checkbox"/> altezza gronda H _____ <input type="checkbox"/> sup. coperta mq _____ <input type="checkbox"/> cubatura mc _____		
TIPOLOGIA		PIANI E DIMENSIONI DI MASSIMA	
VERTICALI	ORIZZONTALI	MANTI DI COPERTURA	PAVIMENTI
<input type="checkbox"/> pietrame <input type="checkbox"/> mattoni <input type="checkbox"/> listata <input type="checkbox"/> paramenti/tufo <input type="checkbox"/> paramento/pietra	<input type="checkbox"/> solai lat. cem <input type="checkbox"/> solai misti <input type="checkbox"/> solai legno <input type="checkbox"/> volte portanti <input type="checkbox"/> volte leggere <input type="checkbox"/> incannicc. <input type="checkbox"/> mattoni in folio <input type="checkbox"/> tetti in C.A. <input type="checkbox"/> tetti in legno	<input type="checkbox"/> coppi <input type="checkbox"/> tegole marsigliesi <input type="checkbox"/> terrazze <input type="checkbox"/> maiolicato	<input type="checkbox"/> cotto <input type="checkbox"/> maiolicato <input type="checkbox"/> graniglia <input type="checkbox"/> pietra
STATO DI CONSERVAZIONE			BENI MOBILI ANNESSI
	Lesioni Leggere	Lesioni Gravi	Perico- losità
			Credito
strutture verticali			
strutture orizzontali			
coperture			
archi - architravi			
volte			
cornicioni			
manto di copertura			
pinnacoli - camp. a vela			
controsoffitto ligneo			
volte incannicciate			
paramenti			
intonaci			
infissi			
pavimenti			
			<input type="checkbox"/> dipinti murali <input type="checkbox"/> sculture lignee; pietra <input type="checkbox"/> stucchi <input type="checkbox"/> soffitti lignei <input type="checkbox"/> cori lignei <input type="checkbox"/> organi <input type="checkbox"/> pulpiti <input type="checkbox"/> tele; tavole <input type="checkbox"/> reperti <input type="checkbox"/> campane <input type="checkbox"/>

$$i_d = \frac{\sum p_i \cdot D_i}{4}$$


→ EMS-98 Damage Level

# CHURCHES




## Toscana




## Piedmont



## Lombardy





# CONVENTS



$Q = 3$	$V = 0.89$
---------	------------

The same vulnerability curve used for the churches is adopted for the convents




# CASTLES

$$Q = 2.7$$

$$V = 0.97$$

Behaviour Modifier

$$\Delta V_1 = 0.2$$




State of maintenance before the seismic event: **ruin**



State of maintenance before the seismic event: **not-ruin**



# BELL TOWER




$$Q = 2$$

$$V = 0.89$$

Limited vulnerability for low macroseismic intensity. Rapid increment of the damage when the seismic severity increases



# CELL OF THE BELL TOWER




$$Q = 1.49$$

$$V = 0.94$$

- Lower displacement capacity for the pier of the cell
- The seismic demand, in term of displacement, is higher for the cell






TIPOLOGY	Q	V
Churches	3.0	0.89
Convents	3.0	0.89
Castles	2.7	0.97
Towers	2.0	0.89
Cells	1.49	0.94



## LEVEL 0: Macroseismic Approach

Typology	V	Q
Palaces	0.62	2.3
Churches	0.89	3.0
Convents	0.89	3.0
Mosques	0.81	2.6
Towers	0.89	2.0
Cells	0.94	1.49

Typology	V	Q
Obelisks	0.74	3
Theaters	0.70	2.3
Castles	0.97	2.7
Triumphal arches	0.58	2.6
Arch Bridges	0.46	2.3



# LEVEL 1: Macroseismic Approach

The vulnerability index is modified taking into account the further information available

<b>State of preservation</b>	worst	+ 0.04	<b>Masonry quality</b>	yes	+ 0.05
	medium	0		no	0
	good	- 0.04		<b>Site morphology</b>	ridge
<b>Damage level</b>	severe	+ 0.04	sloping		+ 0.02
	light	+ 0.02	flat ground		0
	none	0	<b>Plan regularity</b>	<i>It depends from the typology</i>	
<b>Architectural transformations</b>	yes	+ 0.02	<b>Section regularity</b>	<i>It depends from the typology</i>	
	no	0	<b>Position</b>	<i>It depends from the typology</i>	
<b>Recent interventions</b>	yes	+ 0.02			
	no	- 0.02			

- parametri *specifici* per ogni tipologia (ad es. chiese)

<b>Plan regularity:</b> nave typology	central	- 0.02	<b>Domes/Vaults</b>	yes	+ 0.04
	one	0		no	0
		three	+ 0.02	<b>Lateral walls height</b>	low (< 6 m)
<b>Section regularity:</b> raising elements or façade	yes	+ 0.04	medium (> 6 m and < 12 m)		0
	no	0	high (> 12 m)		+ 0.04
<b>Position</b>	included	- 0.02			
	additions	+ 0.02			
	isolated	0			



# SAVE: Strumenti Aggiornati per la Vulnerabilità sismica del patrimonio Edilizio e dei sistemi urbani



Censimento LSU – Parchi: edito dal Dipartimento di Protezione Civile

CHECK - LIST													ISTAT COMUNE			COMUNE		Squadra		LISTA n.								
DATI GENERALI													PARTE "A VISTA"						PARTE "NON A VISTA"									
N. REF. MARIS	PROGRESSIVO	LOCALIZZAZIONE	CARTOGRAFIA DI RIFERIMENTO				N. RIFER. IN CARTA	DENOMINAZIONE	LOCALITÀ O INDIRIZZO	QUOTA	FOTO			POSIZIONE	ACCESSIB.	MORFOLOGIA	STATO CONSERV.	DESTINAZIONE	CONSISTENZA			UTILIZZAZIONE	VINCOLO	PROPRIETÀ	DOCUMENTAZIONE	CODICE T.C.L.	PARCO	DATAZIONE
			QUA	FOG	TAV	ALL					n° Roll	n° foto	altim.						sito	edificio	LU (m.)							
1																												
2																												
3																												
4																												
5																												
6																												
7																												
8																												
9																												
10																												
11																												
12																												
13																												
14																												
15																												

NOTE: Indicare, richiamando il n° progressivo, le eventuali DENOMINAZIONI storiche, le eventuali modalità per l'ACCESSIBILITÀ all'edificio, la fonte della DATAZIONE e il numero Scheda MARIS se esistente


Scheda LSU – Parchi : *check-list* usata per catalogare gli edifici monumentali nelle località situati all'interno dei Parchi Nazionali dell'Italia Medionale.




# Macroseismic Method for monuments– Level 1

Level 1 vulnerability analysis of the cultural heritage for the parks of South of Italy (LSU Park Project)

Distribution of the typology for the 1400 analyzed buildings




# LSU Park Project - Exposure analysis and geocoding



*Number of monumental building for each municipality*

## LSU Park Project - Exposure analysis and geocoding



*Distribution of the typologies of monumental buildings within the municipality of Sicily region*



Chiave	61004451/4 3		61004451/4 4		61004451/4 5	
Istat Comune	61004		61004		61004	
Squadra	45		45		45	
Lista	S. AGOSTINO CHURCH		S. AGOSTINO CONVENT		MONTE DEI PEGNI PALACE	
Protezione	V		0.89		0.62	
Scadenza	Q		3		2.3	
Codice Marisz					3	
Codice Maris3	7		13		10	
Quadrante	4		4		4	
Foglio	3		4		5	
Tavola						
Allegato						
Riferimento Carta						
Denominazione	CHIESA DI S. AGOSTINO		CONVENTO DI S. AGOSTINO		PALAZZO MONTE DEI PEGNI	
Località						
Indirizzo	VIA ROMA P.ZZA S. AGOSTINO		P.ZZA S. AGOSTINO		V. DELL'ANNUNZIATA	
Quota	100		100		100	
Numero Roll	1		1		1	
Numero Foto					6	
Distanza					20	
Posizione					2	
Sito					0	
Edificio					1	
Morfologia					1	
Stato Conservativo	0		0		0	
Destinazione	S62		S32			
Lunghezza	30		33		14	
Larghezza	12		50		6	
Altezza	18		13		11	
Utilizzazione	2		1		1	
Vincolo1	2		2		2	
Vincolo2						
Vincolo3						
Proprieta'	0		0		0	
Documentazione	3		3		1	
Codice TCI	1		1		1	
Parco						
Datazione	XIV		XIV		1687	
Denom storic						
Accessib						
Fonte datazione						
Note						
Memorizzazione	21/10/1998		23/10/1998		23/10/1998	
Codice Istat Regione	15		15		15	
Denom_Parco	Regionale Partenio		Regionale Partenio		Regionale Partenio	

**TYOLOGICAL IDENTIFICATION**  
*Level 0*



Chiave		61004451/4 3	61004451/4 4	61004451/4 5				
Istat Comune		61004	61004	61004				
Squadra		45	45	45				
Lista		S. AGOSTINO CHURCH	S. AGOSTINO CONVENT	MONTE DEI PEGNI PALACE				
Problema								
Scadenza	V <sub>0</sub>	0.89	0.89	0.62				
Località	Q	3	3	2.3				
Coordinate	V	0.87	0.93	0.64				
Quadrante		4	4	4				
Foglio		3	4	5				
Tavola								
Allegato								
Riferimento Carta								
Denominazione		CHIESA DI S. AGOSTINO	CONVENTO DI S. AGOSTINO	PALAZZO MONTE DEI PEGNI				
Località								
Indirizzo		VIA ROMA P.ZZA S. AGOSTINO	P.ZZA S. AGOSTINO	V. DELL'ANNUNZIATA				
Quota		100	100	100				
Numero Roll		1	1	1				
Numero Foto				6				
Distanza				20				
Posizione		<b>TYPOL OGICAL IDENTIFICATION</b>			2			
Sito					<i>Level 0</i>			0
Edificio								1
Morfologia		1	1	1				
Stato Conservativo		0	0	0				
Destinazione		S32	S32					
Lunghezza				14				
Larghezza				6				
Altezza				11				
Utilizzazione				1				
Vincolo1				2				
Vincolo2								
Vincolo3								
Proprieta'		0	0	0				
Documentazione		3	3	1				
Codice TCI				1				
Parco								
Datazione				1687				
Denom storic								
Accessib								
Fonte datazione								
Note								
Memorizzazione		21/10/1998	23/10/1998	23/10/1998				
Codice Istat Regione		15	15	15				
Denom_Parco		Regionale Partenio	Regionale Partenio	Regionale Partenio				

**TYPOL OGICAL IDENTIFICATION**  
*Level 0*


**Position**

**Maintenance**


**Height**




# LSU Park Project - VULNERABILITY ANALYSIS




*Vulnerability index for the palaces*



*Vulnerability index for the churches*



*Vulnerability index for the chapels*




*Vulnerability index for the towers*

# LSU Park Project – HAZARD

Italian Seismic Code (OPCM 3431) PGA map  
Return Period 475 years



PGA






## LSU Park Project – HAZARD

Italian Seismic Code (OPCM 3431) PGA map  
Return Period 475 years


→ PGA

$$I = 5 + \frac{1}{\ln c_2} (\ln a_g - \ln c_1)$$


→ Intensity




# LSU Park Project – DAMAGE SCENARIO




Mean damage for the palaces



Mean damage for the churches



Mean damage for the castles



Mean damage for the bridges


# LSU Park Project – DAMAGE SCENARIO

DENOMINAZIONE	INDIRIZZO	ETA' (ORIGINALE)	LSU-codice	STATO CONSERVATIVO	MORFOLOGIA SITO	POSIZIONE DEL CONTESTO	ALTEZZA PARETI LATERALI	V	Q	I	μd
CHIESA DI SAN FRANCESCO		XVI	80063295/715	worst	ridge	additions	high	1.05	3	9.5	4.391
SANTUARIO DEL BEATO NUNZIO SULPRIZIO	PIAZZA S. GIORGIO	XVII	68029 61/2 7	worst	ridge	additions	high	1.05	3	9.5	4.391
CHIESA DI SANTA MARIA DI LORETO	VIA GALDIERI	1634	66053281/2 5	worst	sloping	additions	high	1.03	3	9.5	4.345
CHIESA DI S.PIETRO		XVII	66054282/4 3	worst	ridge	additions	high	1.03	3	9.5	4.345
CHIESA DEGLI ALAMI		XVIII	66002323/415	worst	sloping	isolated	high	1.01	3	9.5	4.296
CHIESA DEL SS.CORPO DI CRISTO		1800	62030572/2 4	worst	ridge	isolated	high	1.01	3	9.5	4.296
CHIESA DELLA SPIRITO SANTO	MONTE DRAGO STRAPIOMBO DEL FUNNO	940	80011241/2 1	worst	sloping	isolated	high	1.01	3	9.5	4.296
CHIESA DI S. FELICE	LARGO S. DOMENICO	1485	61041611/3 5	worst	sloping	additions	high	1.01	3	9.5	4.296
CHIESA DI SANTA LUCIA	VIA DEL SEMINARIO	VI	69043174/7 4	worst	ridge	additions	medium	1.01	3	9.5	4.296
CHIESA DI SAN SALVATORE	P.ZZA DELLA VITTORIA	XVIII	80063296/7 8	worst	sloping	additions	high	1.01	3	9.5	4.296
CHIESA MADRE S. LUCIA	P.ZA DELLA MISERICORDIA	1348	83052131/410	worst	ridge	additions	medium	1.01	3	9.5	4.296
CHIESA S. MARIA DEL CARMINE	VIA S. GIUSTA	1681	61041612/313	worst	flat ground	additions	high	1.01	3	9.5	4.296
CHIESA S. NICOLA	PIAZZA MARGHERITA	XVI	80060172/2 5	worst	sloping	additions	high	1.01	3	9.5	4.296
CHIESA S.BIAGIO		1546	65018131/2 7	worst	ridge	additions	medium	1.01	3	9.5	4.296
CHIESA S.ROCCO			62029621/412	worst	ridge	isolated	high	1.01	3	9.5	4.296
MADONNA DELLE GRAZIE	CONTRADA BADIA GRANDE	XII	66013 23/4 5	worst	sloping	additions	high	1.01	3	9.5	4.296
S.ANTONIO		XVIII	69062191/212	worst	ridge	additions	medium	1.01	3	9.5	4.296

Database in Access®

# Macroseismic Method for monuments – Consequences assessment

- a synthetic parameter, which allows the definition of a **hierarchy in the seriousness** of the structural damage for the large number of damaged churches;
- the **usability of the church**, defined by the surveyors by an expert judgment.



Although it is impossible to fix a threshold of the damage score, directly connected with the usability, it is possible to notice that for  $id > 0.3$ , almost all the churches surveyed after the Umbria and The Marches earthquake were judged unsafe.

- define the **provisional interventions** (normally we could begin with the most damaged churches), as well as the **first interventions of retrofitting** and also for **programming the final intervention of consolidation**

# Macroseismic Method for monuments – Consequences assessment

## ECONOMIC LOSSES MODEL

The economic losses model was developed taking into account three virtual churches:

	Small church	Medium Church	Large church
Nave dimension (m)	7 × 12	14 × 25	25 × 50
Maximum height (m)	9	12	35
Plan area (m <sup>2</sup> )	84	350	1250

The partial cost related to each collapse mechanism has been evaluated, for three damage levels (light, medium, severe).

<i>LIGHT DAMAGE</i>		<i>MEDIUM DAMAGE</i>		<i>SEVERE DAMAGE</i>	
<u>Damage description</u> Intradossal cracks are localized in the apex stone, for flat or barrel arches, or in proximity of the apex stone for all the other kinds of arches.		<u>Damage description</u> In flat or barrel arches, wide cracks are present in the apex stone and in the skewbacks. Alternatively, two cracks are located near to the intrados of the arch and the opposite skewback. Possibility of small cracks in the lateral piers.		<u>Damage description</u> The crack pattern is analogous to the one described for the <i>medium damage</i> but with an increase of the cracks (with crushing at the base of the piers). Possibility of an arch profile deformation and sliding between the stones.	
<u>Repair and retrofitting</u> Spackling of the cracks. Insertion of a tie-rod or control of the efficiency, if it is already present.		<u>Repair and retrofitting</u> Insertion of a tie-rod in order to eliminate the horizontal thrust (don't inject the holes, to allow the retensioning of the tie-rod). Mortar injections in the cracked areas, in order to repair the masonry.		<u>Repair and retrofitting</u> Propping of the triumphal arches. Insertion of a tie-rod. Repairing of the damaged masonry by mortar injections and insertion of steel bars. In the case of partial collapse, the parts are rebuilt.	
<u>Estimate of quantities</u>	k€	<u>Estimate of quantities</u>	k€	<u>Estimate of quantities</u>	k€
• Insertion of a tie-rod:	1.5	• Insertion of a tie-rod:	1.5	• Insertion of a tie-rod:	1.5
• Spackling and key of the cracks near the apex stone:	0.5	• Mortar injection (20 m <sup>2</sup> ) to consolidate the arch and the lateral piers:	1.7	• Mortar injection (30m <sup>2</sup> ) in the arch and the piers	2.4
• Plaster of the walls:	0.3	• Spackling and key of the cracks in the apex stone and in the skewbacks:	0.8	• Insertion of steel bars in the piers:	2.0
		• Plaster of the walls:	0.5	• Rebuilt of collapsed parts:	2.0
				• Plaster of the walls:	1.3
				• Propping of the arch:	1.8
<u>Cost</u>		<u>Cost</u>		<u>Cost</u>	
2.3 kEuro		4.5 kEuro		11 kEuro	

Triumphal arch:  
damage description,  
proposed interventions  
and estimation of costs  
for the virtual church of  
medium size.